



Skoda Fabia I sedan 1999-2007

PU Side Mouldings

F-11



RH FRONT RH REAR



← FRONT



LH FRONT LH REAR

Degrease/entletten/degraisser/ontvetten
Alcohol/Alkohol/Alcool/Alcohol

1



20-40 °C

2



48^h




5



3

4



Iedere cm goed aandrukken !!
Press very carefully every cm !!
Sehr fest andrücken jeden cm !!

